Oil Field Environmental Incident Summary

Responsible Party: CALIBER MIDSTREAM, LLC **Well Operator:** CALIBER MIDSTREAM, LLC

Well Name: Hay Butte Gas Plant

Field Name: RAWSON Well File #:

Date Incident: 6/29/2014 Time Incident: 08:45 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 101 Sec: 36 Qtr: SE SW

Location Description: Hay Butte Gas Plant

Submitted By: Skip Vest Received By:

Contact Person: Skip Vest

1200 17TH STREET, SUITE 2100

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3 Mile

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 15 Barrels

Brine Other

Description of Other Released Contaminant:

None

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Release was contained within secondary containment.

Potential Environmental Impacts:

None, as release was contained within secondary containment.

Action Taken or Planned:

Designate a crew member to gauge the tanks every three hours. Train crew members on procedures on how to properly gauge tanks.

Wastes Disposal Location: Recovered wastes will be disposed at an approved disposal center by clean up contractor Enviro Shield.

Agencies Involved:

Updates

Date: 6/30/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a tank overflow at a gas plant. Followup necessary to confirm containment and cleanup.

Date: 4/1/2015 Status: Inspection Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 11:18 a.m. The weather is clear, 54°F, with the wind from the west at 30 mph. This site is located in the same area as the gas plant for the company. The tanks for oil are located in the southwestern area of the plant on the south side. The tanks are within a metal containment. Did not see any area that oil flowed off site or out of dike system. No further followup needed. 47.76146; - 103.54840

Date: 6/2/2015 Status: Correspondence Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Requested information on cleanup.

Date: 6/22/2015 Status: Correspondence Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received final report and clearance samples.

Date: 8/19/2015 Status: Inspection Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Sent No Further Action letter to the company in regard to this spill.